

# Pictures Showing Deterioration of the 3<sup>rd</sup> Street SE Bridge

February 13, 2015



Deterioration at Bearing Which Supports the Bridge Span



Deterioration at Stringer Connection Supporting the Metal Deck



Deterioration of the South Pier Cap that Supports Two Bridge Spans



Deterioration at Lower Sidewalk Connection